SOLID WASTE DISPOSAL

	Field Inspection (30)	Office In	retatem ()	W _U Y
ST. CLAIR	Co S.W.D.		RE	EGION: II
	te) / Metro (Responsible F	Parcy)	EPECTOR(S): B	allard
DATE: Oct. 7. 19	70 TIME: P.M.	INTERVIEWED: Charles	Gallamore, Site	Manager
SITE: (Proposed,	Existing), REGISTERED (YE	es, No), APPROVED (Yes		E OPERATION RTED:
OPERATOR/LESSEE: N	detro Disposal ADDRES	: Belleville, Illin	ois PHON	·:
PROPERTY OWNER: N	etro Disposal ADDRESS	Belleville, Illin	ois	
LOCATION: adjac	ent to Fairmont City, Il	linois		
Type of Terra	Range 9 W , Twp. in: Gravel Pit (), Quar Depth Upland (), Lowland	2 N , Sec. 8 rry (), Clay Pit (), (x), Swamp (), Other		
Total Area:	8.5	Area Complete	d :	
ZONING:	NI NI	EAREUT MUNICIPALITY:	Fairmont City	adjacent
<u> </u>				(Dis:ance)
ADJACENT LAND USE:	Residential	NEAREST HOUS	E/BUILDING: 7	5 yards (Distance)
AREAS/COLLECTORS. C	ERVED: East St. Loui			· · · · · · · · · · · · · · · · · · ·
	RECEIVED DAILY: At Prese	no: 20 compactor loads	/.nticipat	ed: (Yes, No)
GYPES OF REFUSE RE	CCEIVED: household			
DIGPOSAL RATEO: \$	DAYS & HRS.	OF OPERATION: 6 days	s per week 8	to 5
•	Open Dump, <u>Landfill</u> , Lan Open Burning, Other		Burning, Appro	ved Incineration
LANDFILL METHOD: TYPE AND CONDITION	Trench, Area Fill, Combi	nation, N/A e: Good	_ On Cite:	Good
		Gate lo	ck	
METHOD OF RESTRICT	TING ENTRANCE TO SITE:	0400, 10		
	TING ENTRANCE TO SITE:			

Ţ	POSITING HAZARDOUS MATERIALS: (Yes, No) Types:
Ē	UIPMENT AVAILABLE: D-7 Cat
	VERING REFUSE DAILY: (Yes, No) DEPTH: 6+" inches, Sufficient Cover Available (Yes, No)
:	Findings:
>	
)	Blowing Litter (Yes, No), Fencing Provided (Yes, No)
⊃ ,	
ထာ ်	OVIDING FINAL COVER: (Yes, No) DEPTH: inches
T	Findings:
	
5	CCTORS: Findings: None
⊃ च	Control Activity:
	MPING IN WATER: (Yes, No) Water Depth:inches, Site Subject to Flooding: (Yes, No)
-	Method of Diverting/Removing Surface Water from Site:
Ö	JRFACE WATER: Creek River Pond Lake (Name) (Name) (Name
0	
!	Distance from Fill (if within & mile), Leachate from Fill into Water (Yes, No
. 7	CLLS (Potable, Non-Potable): Distance from Fill (if within mile) #1Feet/Yards
	#2, #3 Fee:/Yards Feet/Yards
	Sample Taken: #1 (Yes, No), #2 (Yes, No), #3 (Yes, No), Ground Water Level:
	IRE PROTECTION ARRANGEMENTS: Yes
	emarks: Adequate daily cover of all refuse is being provided,
	Richard L. Ballard
	Sanitary Inspector

RLB/skv cc: Region II

PLAT SHOWING Survey Indicating the Location of Sanitary Landfill Site Workings Related to the West Corporation Line of the Village of Fairmont City, Illinois January 3, 1972 : Scale: 1"=400" Sheppard, Morgan & Schwaab, Inc. Consulting Engineers File: Job No. 7204-1 EALAMONTCITY ROAD COLLINSVILLE 0 0 N. W. 1/2 SEC. 8-2-9 N.E.1/4 SEC. 3-2-9 E. GOUND MAIN 5.00 R.R. PENNSYLYMINA 1580